**DOUBLE I-JOIST - Verify detail with EOR (For uniformly top-loaded I-joists only)**

Block thickness should be equal to or slightly thicker than flange overhang.

Sheathing joint over one joist (where occurs)

Gap at bottom flange

Tight fit to top flange

1/8" min. 1/4" max

Assembly Sequence

Step 1 - Nail "A" blocks to face of web on joist "Y" only. Back web during nailing to prevent damage to web flange connection.

Step 2 - Nail "B" blocks to "A" blocks.

Step 3 - Nail through web of joist "Z" to "B" and "A" blocks. Repeat steps 1 through 3 if more than two joists are to be joined.

32" o.c. max.

A
B
Step 3

Step 2

B

Top flange

Web

Bottom flange

A

B

Step 1

3 - 12d common nails clinched if possible

Joist Y

Joist Z